

KILN SAFETY



CHECK TO ENSURE EXHAUST FANS ARE TURNED ON.



EXTERIOR OF KILN WILL BECOME HOT DURING FIRING.



DO NOT LEAVE PAPERS OR COMBUSTIBLES AROUND KILN. ALLOW A MINIMUM OF 18" CLEARANCE ON ALL SIDES OF KILN.



DO NOT UNLOAD KILN UNTIL KILN IS COOL TO THE TOUCH OR 1250°F INSIDE CHAMBER.



BE CAREFUL OF SHARP STILT MARKS ON BOTTOM OF FIRED PIECES.



WEAR GLASSES OR GOGGLES WHEN USING A DREMEL TOOL OR STILT!

GLAZE SAFETY



**CALL LOCAL POISON CONTROL HOTLINE
IF GLAZE IS INGESTED.**



**CLEAN UP GLAZE SPILLS BEFORE THEY
DRY.**



**WIPE GLAZE AREA WITH DAMP CLOTH
DAILY.**



**WIPE TABLE TOPS WITH DAMP CLOTH
DAILY.**



WET MOP FLOORS DAILY – DO NOT SWEEP.



**VACUUMS MUST HAVE A HEPA FILTER
INSTALLED (0.3 MICRONS)**

HOUSEKEEPING RULES

HERE ARE SOME GENERAL RULES THAT SHOULD BE PUT INTO PLACE FOR EVERY STUDIO:



KEEP THE KILN AND/OR DIPPING ROOM(S) NEAT AND CLEAN.



WORKING SURFACES SHOULD BE UNCONTAMINATED BY DUST OR DRIED GLAZE.

Spills should be wiped up promptly from all surfaces (counters, walls, and floors).



AVOID ACTIVITIES THAT GENERATE DUST:

- Sweeping generates dust. Solution: Use a wet mop instead.
- Finger sanding generates dust. Solution: Improved glazing practices.



PARTNER A HEPA FILTER SYSTEM WITH GOOD VENTILATION TO AVOID THE BUILDUP OF FUMES OR DUSTS.



DO NOT EAT, DRINK, OR SMOKE WHEN WORKING WITH CHEMICAL PRODUCTS OR GLAZES.



WASH HANDS AND ARMS THOROUGHLY AFTER WORKING WITH GLAZE.



RINSE MOUTH OR EYES IF SPLASHED WITH GLAZE.



WEAR A CLEAN APRON TO PROTECT CLOTHING.

REMEMBER

**NO SMOKING,
EATING, OR
DRINKING IN
THIS AREA!**