

PanelCraft Installation Guide – Sept. 2021 Update – Release Notes

1. Added new Rake Starter Plates to parts offering.
2. Added module clamp, seam clamps, & hand crimpers to parts offering graphics.
3. Removed all references utilizing clips to start roof panel runs. Replaces with improved Rake Starter Plates.
4. Remove retired perimeter plates (RP-038 & RP-138) from parts offering.
5. Adjusted appearance of eave trim to allow for nesting over new eave plates.
6. Revised notching details at ridge / high side.
7. Lengthened endlap pigtail sealant to 4 in.
8. At the clip locations, added references to slit any insulation 6" or greater.

Note: Updates listed in this document are a general reference to the major changes to the document. Any minor updates and corrections to the document are not listed above. Licensee should review the entire document for compatibility with their current installation guide and installation methods.