





PAA - Exterior Excellence Reports

 Date of Visit
 02/04/2025

 Location Name
 sample NA

 Overall Score
 100% (110 / 110)

EXTERIOR	100% (110 / 110)
As you pulled into the property or drove past the location was it welcoming?	5/5
© Excellent	
Above Average	
○ Good	
○ Below Average	
O Poor	
• NA	
Was the property signage and directionals well maintained and identifiable?	5/5
Excellent	
Above Average	
Good	
○ Below Average ○ Poor	
NA	
Was there a marketing incentive visible to entice a renter to schedule a tour on the exterior grounds or building. Example: Signa that said one month FREE rent.	
Yes	
No	
Was the landscaping tasteful, well maintained and free of debris. Excellent	5/5
Above Average	
Good	
○ Below Average	
O Poor	
NA (Hi-rise)	
Sidewalk condition	5/5
○ Excellent	
O Above Average	
○ Good	
○ Below Average	
OPoor	
• NA	
Were you able to find the leasing office easily as you pulled onto the property.	5/5
Carallent Excellent	
Above Average	
○ Good	
○ Below Average	
O Poor	
NA (Hi-rise)	
Was the leasing office signage well maintained?	5/5
Control Excellent	
Above Average	
Good	
Below Average	
Poor	
NA (Hi-rise)	
Was there reserved parking space for Future Residents or an area identified for leasing office parking? Excellent	5/5
Above Average	
○ Above Average ○ Good	
Selow Average	
Poor	
O 1 001	
○ NA	

Did the property have handicapped parking options?	5/5
Excellent	
Above Average	
Good	
○ Below Average	
Poor	
• NA	
Were curbs, driveways, steps, walkways, clean, in good condition, and free of litter?	5/5
○ Excellent	
○ Above Average	
Good	
○ Below Average	
O Poor	
○ NA	
Parking areas free of disabled cars, boats, RV's	5/5
© Excellent	-,-
○ Above Average	
Good	
○ Below Average	
O Poor	
○ NA	
Were the overall buildings exterior condition clean, in good condition, and free of litter? Excellent	5/5
○ Above Average	
○ Good	
○ Below Average	
Poor	
• NA	
Were balconies and terraces well maintained, clean	5/5
Excellent	
Above Average	
Good	
Below Average	
Poor	
O NA	
Building Siding/Brick/Painted surface, fresh without damage and clean Excellent	5/5
○ Above Average	
Good	
○ Below Average	
○ Poor	
• NA	
Windows clean	5/5
○ Excellent	
○ Above Average	
○ Good	
○ Below Average	
○ Poor	
• NA	
Fencing straight and clean	5/5
○ Excellent	
- Licellett	
Above Average	
○ Above Average	
○ Above Average○ Good	

Exterior Amenities well maintained, clean and free of litter		5/5
○ Excellent		
Above Average		
Good		
Below Average		
Poor		
• NA		
• IVA		
		F (F
Curbs, fire lanes clearly marked		5/5
Excellent		
O Above Average		
Good		
Below Average		
OPoor		
○ NA		
Asphalt maintained with no visible potholes		5/5
○ Excellent		
Above Average		
Good		
Below Average		
Poor		
NA (Hi-rise)		
City III 199		F (F
Sidewalk condition		5/5
Excellent		
○ Above Average		
Good		
Below Average		
OPoor		
○ NA		
Speed bumps clearly marked		5/5
○ Excellent		
Above Average		
○ Good		
Below Average		
OPoor		
ONA (Hi-rise)		
Overall, did the signage allow you to navigate the community and see all of it	t benefits?	5/5
○ Excellent		
Above Average		
Good		
Below Average		
O Poor		
NA (Hi-rise)		
VIA (III-IISE)		
Paged on the architectural coelities have likely and a coelities to a coelities t	as sammunity?	E /E
Based on the architectural qualities how likely are you to schedule a tour of the	ne community?	5/5
• Very Likely		
Likely		
○ Maybe		
O Not Likely		
○ Not Happening		
NOTES (detail any thing that was less than Excellent):		
sample NA		